



# Fleet Incident Report and Lesson Learned

FIR # 1

Distribution Date: 12 Jan 2015

Action Item Due: YES

## Incident Report

### What Went Wrong

On October 21, 2014, the medic suffered minor abrasions and lacerations while showering when the curved tempered glass shower surround shattered. The medic slipped and fell on the glass fragments. Drainage was inadequate despite to previous attempts to repair the drain. There was no non-skid surface to prevent the slip and no grab bar or safety rail to prevent the fall.

### What was done to correct it at the time

The glass shower was removed and replaced with a vinyl shower curtain. A hand rail and non-skid floor cover were installed in the shower.

### Actions you need to take to prevent a similar incident on your vessel:

Department	Responsible Person	Action to take	To be Completed by Date
Engineering	Chief Engineer	Inspect all showers for non-skid surface on the floor and grab bars or safety rails on the walls. Order and install these items in any shower that does not have them. <b>Report completion</b> only <b>after</b> both non-skid and a grab bar or safety rail have been installed in every shower.	<b>31 Jan 2015</b>  Report completion to <a href="mailto:HSE@tdi-bi.com">HSE@tdi-bi.com</a>

### Approvals

Prepared by:   
Assistant HSE Manager

Approved by:



Pete Tatro, DPA



Dr. James Howell, HSE Manager